BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Development of Playground at ward no. 17 at JP Park.
2	Administration Approval & Date	CE/Lakes/AS/27/12-13 Dtd: 20.12.2012
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/546/2016-17 Dtd: 31.03.2017
4	Estimate Amount	1,00,00,000/-
5	Job Code No.	017-12-000058
6	P-Code	P-2375
7	Agreement No and Date:	EE-3/Lakes/AG/08/2013-14 Dtd: 19.02.2014
8	Work order Number & Date	EE-2/Lakes/WO/08/13-14 Dtd: 19.02.2014
9	Contract Amount as per Agreement	Rs. 1,07,62,686/-
10	Bill Amount	Rs. 1,07,59,017/-
11	S.B.R No. & Date	AEE/YPR/SBR/11/17-18 Dtd: 27.06.2017
12	Agency	N.M. Krishna Murthy
13	M.B. Number & Page No. of Measurement records	3662/16-17 Page No 366187 to 366189
14	Date of Inspection	08.08.2017
15	Enclosures	1) Extract of MB No. 3662/16-17 page no 366189 2) ..... Number of photos taken during inspection
16	Inspection Report	The above site Location has been Inspected by me along with the Concerned person, as per EE(RRN) Letter no EE/RRN/PR/1367/17-18 Dated 7-8-2017. It is observed that the Items indicated in the MB, are not susceptible for measurements, as such the photos taken during the execution of work have been scrutinised and Inspected, it appears that the above work has been done as is satisfactory

EE (RRN) Division, RR Nagara Zone.

8/8/2017

(R. Sathyanarayana)
Inspection Report Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner